

Spectralink 72x2-Series

Release Notes Q1, 2016

Firmware Version PCS 16B

Table of Contents

Introduction	3
Terms and Definitions	3
Release	3
Driver for the Handset Management Cradle	3
Upgrading the Handset	3
Changes	4
Version PCS 16B – Q1, 2016	4

Introduction

Terms and Definitions

- HMP Handset Management Program for Spectralink 75-, 76-Series and 77-Series
- KWS KIRK Wireless Server
- MSF Message Service Format. Contact compliance@spectralink.com for detailed information
- PBX Private Branch Exchange (IP/Lync/CUCM/Analog)
- PCS Product Change Status
- P-ID Production Identification

Release

These combined release notes apply to the released versions of firmware for the Spectralink 72x2-Series. This version specifically applies to version PCS 16B of the firmware. The release is a main release that replaces the PCS 15Q release as the latest generally available (GA) release.

The current handset firmware PCS information can be found in Menu/Status/General information under Firmware. The version consists of two digits and two letters. The digits and first letter forms the major version. The last letter, which can be either small or capital, is the minor version.

Minor versions are irrelevant for these release notes and are therefore left out.

Driver for the Handset Management Cradle.

Ensure that the latest driver is installed. You can download it [here](#)>>

Upgrading the Handset

Download the latest software for (product name) from the [Spectralink Support Portal](#)). Sign up for Spectralink's technical newsletter [Tech Point](#) to get updated on new software releases and technical information.

Also, you can quickly and easily update your handset(s) with the [Spectralink Handset Software Updater](#).

Changes

Version PCS 16B - Q1, 2016

Added or Changed Features

- Updated battery parameters for optimal utilization of the battery capacity.
- Added service menu *99947* to set absent mode.
- Added idle screen battery indicator.
- Improved backwards compatibility for Handset Management Tool, and support for adjusting ear gain, microphone attenuation, and reading custom logo.
- Speed dial entry is now deleted if corresponding phone book contact is deleted.
- Fixed setting the time and date manually.
- Fixed text being truncated on MenuSelectSetupReq.
- Fixed LEDs blinking on MenuSelectSetupReq and AsciiStrReq.